OKLAHOMA LANDMARKS INVENTORY NOMINATION

Oklahoma Historic Preservation Survey, Oklahoma State University, 502 Math-Science Bldg., Stillwater, OK 74078

SOURCE OF NOMINATION: Contract Survey

SCHULTER SCHOOL CAMPUS (Four buildings)

LOCATION: Schulter, Oklahoma 040, Okmulgee County 111

CLASSIFICATION: buildings; public; public acquisition--N/A; occupied; unrestricted; present use--educational

OWNER: Schulter Board of Education, Box A, Schulter, OK 74460

LOCATION OF LEGAL DESCRIPTION: Okmulgee County Courthouse, Okmulgee, OK 74447

DESCRIPTION: excellent condition; altered; original site

The Schulter School campus features four WPA buildings: one classroom building, one privy, a Home Economics Cottage, and a gymnasium/auditorium. The gymnasium/auditorium is a single-story, rectangular ($89' \times 56'$) building constructed of coursed and rusticated native stone of buff color. The roof is arched and has parapets. A rain shelter has been added to the doorway. Some windows have been filled with concrete cinder blocks and others with green plastic. These alterations do not impeach the integrity of the structure.

The Home Economics Cottage has one or two rooms and is a single-story, rectangular $(33' \times 49')$ structure constructed of coursed and rusticated native stone of buff color. The roof is gabled. The entrance is recessed behind a cross gable supported by poles and contains pediments. The sash windows in front are arranged in groups of three and reach to the eaves, smaller windows on all other sides have concrete lentils and sills. Many of these windows have been made smaller by inserting wood or completely filled in with wood.

The classroom building is a single-story, T-shaped (92' \times 100') building constructed of coursed and rusticated native stone of buff color. Red brick was used to make designs on the front. The roof is flat with parapets. Two of the front windows were arched. The recessed entryway is framed by pilasters that give the school an art deco flavor. The window openings have white painted wood inserted, and smaller windows have been installed.

The privy is a rectangular $(23' \times 20')$ building constructed of coursed and rusticated native stone of buff color. The roof is gabled with an attached entryway that has a gabled porch. This entryway has an arched window, and the door is recessed behind an archway. The windows have concrete sills. Four windows have been filled in--three with wood, and one arched window with cinder blocks. Alterations do not impeach the integrity of the structure.

SIGNIFICANCE: 1937 and unknown; builder/architect: unknown

These buildings are significant because construction of them provided many jobs for unskilled and unemployed workers in and around the town of Schulter. These projects enabled the infusion of wages of some 40,000 man-hours of labor into the local community. Educational opportunities were greatly enhanced in this small community through this WPA project. Architecturally, these buildings are unique in terms of type, style, scale, materials, and workmanship. This major project of four structures is significant to the town of Schulter in that these buildings provide the basis for educational opportunities throughout the area. In addition, the WPA eight-hole privy was the largest in Oklahoma.

GEOGRAPHICAL DATA:

Acreage: Less than two acres

Quadrangle: Okmulgee South, Okla. 1:24,000/7.5 min.

UTM: A-15 231660 3933860; B-15 231720 3933860; C-15 231720 3933830; D-15 231680 3933790

VERBAL BOUNDARY DESCRIPTION: Block 4, Burgess Addition to Schulter original.

PICTURE REFERENCE: 95-a; 95-b; 95-c; 95-d; 95-e; 95-f; 95-g; 95-h